

***BERSCH & ASSOCIATES LTD.***

December 31, 2011

Regina Qu'Appelle Health Region  
1440 - 14th Avenue  
Regina, SK  
S4P 0W5

**ATTENTION: Todd Macdonald**

**SUBJECT: Emergency Medical Services – Annual Asbestos Assessment 2011**

Dear Mr. Macdonald,

Bersch & Associates Ltd. was retained by the Regina Qu'Appelle Health Region to conduct an annual asbestos assessment of the Emergency Medical Services facility in Regina, Saskatchewan. The purpose of the annual assessment was to identify any change in condition of the friable Asbestos Containing Materials (ACM) located within the facility. The assessment entailed the inspection of friable asbestos-containing materials identified in the 2010 Asbestos Audit.

The annual assessment forms an integral component of the asbestos management plan for the facility and helps maintain compliance with the Province of Saskatchewan Occupational Health and Safety Act and Regulations. This assessment, along with the asbestos audit database, shall be reviewed with all trades entering the facility to perform maintenance or renovation activity. This will ensure that all parties are familiar with the types and locations of asbestos-containing materials present within the facility. This will also prevent any uncontrolled disturbance of the asbestos materials and possible exposure to asbestos.

The 2010 Asbestos Audit completed within the facility revealed the presence of the following friable asbestos-containing materials: pipefitting compound

No change in condition of the materials was noted in the 2011 assessment.

Sincerely,

Trent Blaus/Wes Berschiminsky  
Bersch & Associates Ltd.

File: R12LL31

EMS Regina			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
	101	North Garage	Sample Rep.	B01-ASB.7	25-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	2nd Floor Storage - Pipeline fitting on small line overhead in the center of room	Pipeline Fitting Compound	Low	Manage	Annual inspection 2011 - No change in condition.	
M	117	South Garage	Sample Rep.	B01-ASB.7	25-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	2nd Floor Storage - Pipeline fitting on small line overhead in the center of room	Pipeline fitting Compound	Low	Manage	Annual inspection 2011 - No change in condition.	
M	136	Corridor	Sample	B01-ASB.6	25-Feb-10	Chrysotile	40%	Pipeline Fitting Compound	Mod/Good	3	136 Corridor - Pipeline fitting on small line above ceiling tile adjacent 137	Pipeline Fitting Compound	Low	Remove	Annual inspection 2011 - No change in condition.	
M	142	Office	Sample Rep.	B01-ASB.6	25-Feb-10	Chrysotile	40%	Pipeline Fitting Compound	Good	3	136 Corridor - Pipeline fitting on small line above ceiling tile adjacent 137	Pipeline fitting Compound above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	144	Secure Files	Sample Rep.	B01-ASB.6	25-Feb-10	Chrysotile	40%	Pipeline Fitting Compound	Good	3	136 Corridor - Pipeline fitting on small line above ceiling tile adjacent 137	Pipeline fitting Compound above closed ceiling space	Low	Manage	Annual inspection 2011 - No change in condition.	
M	145	Washroom	Sample Rep.	B01-ASB.6	25-Feb-10	Chrysotile	40%	Pipeline Fitting Compound	Good	3	136 Corridor - Pipeline fitting on small line above ceiling tile adjacent 137	Pipeline fitting Compound above closed ceiling space	Low	Manage	Annual inspection 2011 - No change in condition.	
2		Second Floor Storage (Above 106 & 117.2)	Sample	B01-ASB.7	25-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	2nd Floor Storage - Pipeline fitting on small line overhead in the center of room	Pipeline Fitting Compound	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Mechanical Room	Sample	B01-ASB.1	25-Feb-10	Chrysotile	60%	Mud compound	Good	3	225 - Mechanical Room - Parging mud beneath the canvass on duct work	Pipeline Fittings, Mud Compound, Duct Expansion Gasket	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Mechanical Room	Sample	B01-ASB.2	25-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	225 - Mechanical Room - Pipeline fitting on small line at waist height in the southeast corner	Pipeline Fittings, Mud Compound, Duct Expansion Gasket	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Mechanical Room	Sample	B01-ASB.3	25-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	225 - Mechanical Room - Pipeline fitting on small line adjacent furnace in the	Pipeline Fittings, Mud Compound, Duct Expansion Gasket	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Mechanical Room	Sample	B01-ASB.4	25-Feb-10	Chrysotile	80%	Asbestos Gasket	Good	3	225 - Mechanical - Duct work gasket on "Supply Air" duct in northwest corner	Pipeline Fittings, Mud Compound, Duct Expansion Gasket	Low	Manage	Annual inspection 2011 - No change in condition.	