

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
B	B18	Basement Boiler Room	Sample	B01-ASB.1	22-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	Pipeline fitting on small "Domestic Cold Water Hard" south of entry adjacent electrical panel "Fan 1 S Laundry"	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.2	22-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	Pipeline fitting on small "Domestic Cold Water Soft" south of entry adjacent electrical panel "Fan 1 S Laundry"	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.3	22-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Moderate	2	Pipeline fitting on medium "Hot Water Return" line south of entry	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B18	Basement Boiler Room	Sample	B01-ASB.4	22-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Poor	1	Pipeline fitting on medium "Hot Water Supply" line south of entry	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B18	Basement Boiler Room	Sample	B01-ASB.7	22-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Poor	1	Pipeline fitting on small "Steam" line south of entry above steam generator (blue unit)	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B18	Basement Boiler Room	Sample	B01-ASB.8	22-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Pipeline fitting on small " Hot Water Return" line adjacent fire exit staircase	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.9	22-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Good	3	Pipeline fitting on Medium " Hot Water Supply" line adjacent fire exit staircase 1' off the ground	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.10	22-Feb-10	Amosite	80%	Fireproofing	Mod/Good	2	Fireproofing material on ceiling surface	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Moderate	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.12	22-Feb-10	Chrysotile	70%	Fire-Stop Material	Moderate	2	Fire stop material in southwest corner overhead at pipe penetration into west wall	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B18	Basement Boiler Room	Sample	B01-ASB.14	22-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Good	3	Pipeline fitting on medium line at ground level between boilers 1 and 2	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.15	22-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	Pipeline fitting on small "Domestic Cold Water Supply" line overhead adjacent soft water storage tank	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.17	22-Feb-10	Chrysotile	70%	Mud compound	Good	3	Mud compound beneath canvass on duct in northeast corner	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B18	Basement Boiler Room	Sample	B01-ASB.18	22-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Pipeline fitting overhead adjacent entry	Pipeline Fitting Compound, Mud Compound beneath canvass, Fireproofing, Fire-Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Generator Room	Sample Rep.	B01-ASB.18	22-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Generator Room - Pipeline fitting overhead adjacent entry	Pipeline Fitting Material	Moderate	Repair	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Laundry Room	Sample	B01-ASB.22	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	1	Laundry Room - Pipeline fitting on medium line above ceiling tile adjacent large ironing unit (mangler)	Pipeline Fitting Material above suspended ceiling	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
B		Laundry Room	Sample	B01-ASB.20	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Poor	1	Laundry Room - Pipeline fitting remnants on top of ceiling tile	Pipeline Fitting Material above suspended ceiling	Mod/High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Laundry Storage Room	Sample	B01-ASB.21	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Poor	1	Laundry Storage Room - Sheet flooring, small irregular shapes cream and brown shades	Asbestos Sheet Flooring, Pipeline Fitting Material	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Laundry Storage Room	Sample Rep.	B01-ASB.22	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Laundry Room - Pipeline fitting on medium line above ceiling tile adjacent large ironing unit (mangler)	Asbestos Sheet Flooring, Pipeline Fitting Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Shute Room	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Basement Corridor	Sample	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Basement Corridor	Sample	B01-ASB.29	23-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Good	3	Basement Corridor - Pipeline fitting above ceiling tile adjacent room 126 (Classroom)	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Basement Corridor	Sample	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Basement Corridor	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Auditorium	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Auditorium	Sample	B01-ASB.26	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	1	Auditorium - Pipeline fitting on small line above ceiling tile adjacent kitchen entry	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B6	Women's Washroom/ Change Room	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B6	Women's Washroom/ Change Room	Sample	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Transite Soil Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B 9	Mechanical Room	Sample	B01-ASB.30	23-Feb-10	Chrysotile	20%	Fire-Stop Material	Moderate	2	B9 Mechanical - Fire-stop material adjacent entry at pipe penetration	Pipeline Fitting Compound, Fire-stop Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B 9	Mechanical Room	Sample	B01-ASB.31	23-Feb-10	Chrysotile	60%	Pipeline Fitting Compound	Moderate	2	B9 Mechanical - Pipeline fitting on small "Hot Water Return" line	Pipeline Fitting Compound, Fire-stop Material	Moderate	Repair	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B 9	Mechanical Room	Sample	B01-ASB.32	23-Feb-10	Chrysotile	60%	Mud compound	Moderate	2	B9 Mechanical - Mud at duct adjacent fan control box "SR-27"	Pipeline Fitting Compound, Fire-stop Material	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B 9	Mechanical Room	Sample	B01-ASB.33	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	1	B9 Mechanical - Pipeline fitting on small line overhead adjacent "SF4SA.T" to the north of duct	Pipeline Fitting Compound, Fire-stop Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
B	010	Storeroom	Sample	B01-ASB.59	09-Mar-10	Chrysotile	20%	Pipeline Fitting Compound	Moderate	3	B10 Storeroom - Pipeline fitting on small line east of entry in southeast corner above head	Pipeline Fitting Material	Moderate	Manage	Annual inspection 2011 - No change in condition.	
B	010	Storeroom	Sample	B01-ASB.60	09-Mar-10	Chrysotile	20%	Pipeline Fitting Compound	Moderate	3	B10 Storeroom - Pipeline fitting on small line east of entry in southeast corner overhead	Pipeline Fitting Material	Moderate	Manage	Annual inspection 2011 - No change in condition.	
B		Linen Storage	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B13	Storage	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B12	Maintenance Office	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B5	House Keeping office	Sample Rep.	B01-ASB.21	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Sheet flooring, small irregular shapes cream and brown shades	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B5	House Keeping office	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	- Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B4	Men's Washroom/ Change Room	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Locker Room	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Compound, Transite Soil Pipe	Low/Mod	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Locker Room	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Pipeline Fitting Compound, Transite Soil Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B3	Physiotherapy Room	Sample Rep.	B01-ASB.21	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Sheet flooring, small irregular shapes cream and brown shades	Asbestos Sheet Flooring, Pipeline Fitting Compound	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B3	Physiotherapy Room	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Asbestos Sheet Flooring, Pipeline Fitting Compound	Mod/High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Telephone Equipment	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Compound, Transite Soil Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
B		Telephone Equipment	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	- Medium transite soil pipe in ceiling space adjacent large access hatch	Pipeline Fitting Compound, Transite Soil Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
B		Transformers and Electrical Distribution	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Material	Low	Manage	Annual inspection 2011 - No change in condition.	
B	126	Classroom	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	1	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Compound, Asbestos Sheet Flooring	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	126	Classroom	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
B	B8	Hair Dressing/ Barber	Sample Rep.	B01-ASB.21	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Moderate	2	Sheet flooring, small irregular shapes cream and brown shades	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low/Mod	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B	B8	Hair Dressing/ Barber	Sample Rep.	B01-ASB.57	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	3	Basement Corridor - Pipeline fitting on small foil wrapped line adjacent laundry room	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
B		Duct Shaft	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Transite Soil Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Main Floor Corridor to Sisters Residence	Sample	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material	Low/Mod	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Main Floor Corridor to Sister Residence	Sample	B01-ASB.40	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line adjacent room 106 above ceiling tile	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	101	Dinning	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	102	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	102	Wash Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	102	Wash Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	103	Kitchen	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	103	Kitchen	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	104	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	104 & 106	Wash Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	104 & 106	Wash Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	106	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	107	Bath	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	4	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	108	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Mod/High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	108/110	Wash Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	108/110	Wash Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	109	Hair	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	109	Hair	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Moderate	Manage	Annual inspection 2011 - No change in condition.	
M	110	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	112	Sister's Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	113	Bathroom	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	113	Bathroom	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound, Asbestos Sheet Flooring	Mod/High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	115	Lounge	Sample	B01-ASB.41	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Poor	1	115 Lounge - Pipeline fitting on small line adjacent window above ceiling tile	Pipeline Fitting Compound, Asbestos Sheet Flooring	Mod/High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	115/112	Wash Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound, Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M		East Corridor Sister's Residence	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	117	Private Dining	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	124	Kitchen	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	124	Kitchen	Sample Rep.	B01-ASB.56	23-Feb-10	Chrysotile	20%	Mud compound	Moderate	2	1st Floor Dining Room - Roof drain mud compound, lying on top of ceiling tiles adjacent roof drain above ceiling tile	Roof Drain Mud Compound	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Kitchen Storage	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Staff Dining Room	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Mud Compound above ceiling tile	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Staff Dining Room	Sample	B01-ASB.56	23-Feb-10	Chrysotile	20%	Mud compound	Poor	1	1st Floor Dining Room - Roof drain mud compound, lying on top of ceiling tiles adjacent roof drain above ceiling tile	Asbestos Sheet Flooring, Mud Compound above ceiling tile	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Res Dining	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M	122	Personal Office	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	132	Support Services	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Pipeline Fitting Compound above suspended ceiling, Asbestos Sheet Flooring, Heat Shield Material	Low	Manage	Annual inspection 2011 - No change in condition.	
M	132	Support Services	Sample	B01-ASB.62	23-Feb-10	Chrysotile	60%	Heat Shield Material	Poor	2	132 Office - Heat shield in light fixture	Pipeline Fitting Compound above suspended ceiling, Asbestos Sheet Flooring, Heat Shield Material	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	132	Support Services	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Compound above suspended ceiling, Asbestos Sheet Flooring, Heat Shield Material	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Janitor Closet	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Staff Washroom	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M		Center Staircase	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	134	Office	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	134	Office	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		West Corridor	Sample	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Linen adjacent 136	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Pipeline Fitting Material above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	136	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	136	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	137	Res Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	137	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	138	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	- Sheet flooring, white and grey small stone pattern with	Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	138	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	1	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	139	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	139	Res Room	Sample Rep.	B01-ASB.39	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	1	Main Floor Corr. to Sisters Res - Pipeline fitting on small line above ceiling tile within wall cavity	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	140	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	140	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	141	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	141	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Good	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	142	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	142	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	143	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Mod/Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	143	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Moderate	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	144	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	144	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor/Mod	2	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M	145	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	145	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Good	3	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	146/148	Res Room	Sample	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	146/148	Res Room	Sample	B01-ASB.38	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	Pipeline fitting on small line above ceiling tile in the northeast corner	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
M	147	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M	147	Res Room	Sample Rep.	B01-ASB.36	23-Feb-10	Chrysotile	50%	Pipeline Fitting Compound	Poor	1	Main Floor West Corridor - Pipeline fitting on small line in hallway adjacent room 145 above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2		East Corridor	Sample	B01-ASB.44	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	2nd Floor Corridor - Pipeline fitting on small line above ceiling tile adjacent room 211	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		East Corridor	Sample	B01-ASB.61	09-Mar-10	Chrysotile	30%	Asbestos Sheet Flooring	Good	3	2nd Floor Corridor - Sheet flooring, irregular stone pattern with tones of tan and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	201	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	201	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	202	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	202	Res Room	Sample	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	1	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	203	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	203	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	204	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	204	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
2	205	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	205	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	206	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	206	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	207	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	207	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	208	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	208	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	209	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	209	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	210	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	210	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	211	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	211	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	212	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	212	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	212	Res Room	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
2	213	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	213	Res Room	Sample Rep.	B01-ASB.46	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	202 Res Room - Pipeline fitting in northeast corner above ceiling tile	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		Main Dinning Area	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		Main Dinning Area	Sample Rep.	B01-ASB.44	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	2nd Floor Corridor - Pipeline fitting on small line above ceiling tile adjacent room 211	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2		Main Corridor/Vestibule	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		Main Corridor/Vestibule	Sample Rep.	B01-ASB.44	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	2nd Floor Corridor - Pipeline fitting on small line above ceiling tile adjacent room 211	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		West Corridor	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		West Corridor	Sample Rep.	B01-ASB.44	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	2nd Floor Corridor - Pipeline fitting on small line above ceiling tile adjacent room 211	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2		Storage room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2		Storage room	Sample Rep.	B01-ASB.44	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	3	2nd Floor Corridor - Pipeline fitting on small line above ceiling tile adjacent room 211	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	218	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	218	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	220	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	220	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	221	Janitor Closet	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	221	Janitor Closet	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
2	222	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	222	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	225	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	226	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	226	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	227	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	227	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	228	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	228	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	229	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	229	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	230	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	230	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	231	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	231	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	232	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
2	232	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	233	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	233	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	234	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	234	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	235	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	235	Res Room	Sample	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
2	236	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
2	236	Res Room	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3		East Corridor	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		East Corridor	Sample	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	301	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	301	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	302	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	302	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	303	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	303	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
3	304	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	304	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Repair	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	305	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	305	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	306	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	306	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	307	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	307	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	308	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	308	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	309	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	309	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	310	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	310	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	311	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	311	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	312	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
3	312	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	312	Res Room	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	313	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	313	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	313	Res Room	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		Dinning Area	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3		Dinning Area	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		Main Corridor/Vestibule	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		Main Corridor/Vestibule	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		Main Corridor/Vestibule	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Asbestos Sheet Flooring, Pipeline Fitting Compound & Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		West Corridor	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		West Corridor	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	321	Janitor Closet	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Poor/Mod	2	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low/Mod	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3		Hallway to 324 Bath	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3		Hallway to 324 Bath	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	324	Bath	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
3	375	Storage	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	378	Medicine Preparation	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	318	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	318	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	320	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	320	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	322	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	322	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	325	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	325	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	326	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	326	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	327	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	327	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	328	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	328	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Moderate	2	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	329	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
3	329	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	330	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	330	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	331	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	331	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	332	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	332	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor/Mod	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Mod/High	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	333	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	333	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	334	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	334	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	335	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	335	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
3	336	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
3	336	Res Room	Sample Rep.	B01-ASB.47	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Poor	1	3rd Floor East Corridor - Pipeline fitting above ceiling tile across the hall from 311	Asbestos Sheet Flooring, Pipeline Fittings above suspended ceiling	High	Repair/Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
4		East Corridor	Sample Rep.	B01-ASB.56	23-Feb-10	Chrysotile	20%	Mud compound	Poor	1	1st Floor Dining Room - Roof drain mud compound, lying on top of ceiling tiles adjacent roof drain above ceiling tile	Mud Compound	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
4		East Corridor	Sample Rep.	B01-ASB.50	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	4th Floor West Corridor - Pipeline fitting on medium line above ceiling tile adjacent room 475 storage	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4		East Corridor	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	401	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	402	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	403	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	404	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	405	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	406	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	407	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	408	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	409	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	410	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	411	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	412	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4		Dinning Room	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
4		Dinning Room	Sample Rep.	B01-ASB.50	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	4th Floor West Corridor - Pipeline fitting on medium line above ceiling tile adjacent room 475 storage	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4		Main Corridor/Vestibule	Sample Rep.	B01-ASB.50	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Moderate	2	4th Floor West Corridor - Pipeline fitting on medium line above ceiling tile adjacent room 475 storage	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Moderate	Manage	Annual inspection 2011 - No change in condition.	
4		Main Corridor/Vestibule	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4	474	Clean Utility	Sample Rep.	B01-ASB.27	23-Feb-10	Chrysotile	60%	Transite Pipe	Good	4	B6 Women's Wash - Medium transite soil pipe in ceiling space adjacent large access hatch	Transite Soil Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4		West Corridor	Sample	B01-ASB.50	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Moderate	2	4th Floor West Corridor - Pipeline fitting on medium line above ceiling tile adjacent room 475 storage	Pipeline Fitting Material above suspended ceiling	Low/Mod	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
4		West Corridor	Sample Rep.	B01-ASB.25	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Basement Corridor - Sheet flooring, medium sized irregular shapes, different shades of cream and brown	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4		West Corridor	Sample Rep.	B01-ASB.56	23-Feb-10	Chrysotile	20%	Mud compound	Poor	1	1st Floor Dining Room - Roof drain mud compound, lying on top of ceiling tiles adjacent roof drain above ceiling tile	Mud Compound	High	Cleanup/Manage	Annual inspection 2011 - All necessary repairs / removals have been completed.	
4	421	Janitor Closet	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4	421	Janitor Closet	Sample Rep.	B01-ASB.43	23-Feb-10	Chrysotile	30%	Pipeline Fitting Compound	Good	3	235 Res Room - Pipeline fitting above ceiling tile adjacent window	Asbestos Sheet Flooring, Pipeline fittings above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
4	418	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	420	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	422	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	425	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	426	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	427	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	

Santa Maria Senior Citizens Home			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
4	428	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	429	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	430	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	431	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	432	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	433	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	434	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	435	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
4	436	Res Room	Sample Rep.	B01-ASB.34	23-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	146 - Res Room - Sheet flooring, white and grey small stone pattern with orange/brown background	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
5		Fifth Floor Penthouse Mechanical Room	Sample	B01-ASB.51	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Moderate	2	5th Floor Penthouse Mech Rm - Pipeline fitting on medium line at head height east of entry	Pipeline Fitting Material, Fire- Stop Material	Moderate	Remove	Annual inspection 2011 - All necessary repairs / removals have been completed.	
5		Fifth Floor Penthouse Mechanical Room	Sample	B01-ASB.52	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	5th Floor Penthouse Mech Rm - Pipeline fitting on small line east of entry along the floor	Pipeline Fitting Material, Fire- Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
5		Fifth Floor Penthouse Mechanical Room	Sample	B01-ASB.53	23-Feb-10	Chrysotile	20%	Fire-Stop Material	Good	3	5th Floor Penthouse Mech Rm - Fire-stop material at pipe penetration into floor east of entry	Pipeline Fitting Material, Fire- Stop Material	Low	Manage	Annual inspection 2011 - No change in condition.	
5		Elevator Room	Sample Rep.	B01-ASB.52	23-Feb-10	Chrysotile	20%	Pipeline Fitting Compound	Good	3	5th Floor Penthouse Mech Rm - Pipeline fitting on small line east of entry along the floor	Pipeline Fitting Material above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	